

LCC/SRBC3

Appendix 9

Photographs of Site

Photographs of Site



Photo 1: Flag Lane West of Bridge Footpath 58 Public Right of Way through field with horses.



Photo 2: Lord's Lane. Bin out for refuse collection. Note limited scope for passing vehicles. Lord's Lane meets Bee Lane at it's northern end.



Photo 3: Lord's Lane junction with Bee Lane.



Photo 4: Bee Lane/Moss Lane Junction taken from Bee Lane. Note that beyond is not adopted Highway but is an access route for existing dwellings.



Photo 5: Bee Lane Bridge. No separation of users and no protection of parapets. Parapet walls are low.



Photo 6: Bee Lane/Leyland Road junction. Note poor visibility and limited space for queuing vehicles beyond bridge.



Photo 7: Bee Lane Bridge is owned by Network Rail.



Photo 8: Bee Lane with Vehicle. Limited width for passing vehicles and scope for conflict with pedestrians and cyclists. Note vehicle is off the carriageway to enable sufficient passing space.



Photo 9: Equestrian on Bee Lane. Note limited space for vehicles to pass by.



Photo 10: Equestrian on Bee Lane. Note there are a number of accesses on Bee Lane.